


EXPLOSION-DRAWING / SPAREPARTS-OVERVIEW

EXPLOSIONSZEICHNUNG / ERSATZTEILLISTE



Ergometer X100-C

Number in explosion drawing	Item number	Description
1	SP_X100-C_01	Console
2	SP_X100-C_02	Handlerail cap
3	SP_X100-C_03	Handlerail foam
5	SP_X100-C_05	Pulse sensor
6	SP_X100-C_06	Hexagon socket round head cap bolt M8x35
7	SP_X100-C_07	Curved washer M8 -T2
8	SP_X100-C_08	Pulse sensor cable
9	SP_X100-C_09	Resistance band
10	SP_X100-C_10	Resistance band hook
12	SP_X100-C_12	Sensor cable with plug
13	SP_X100-C_13	Resistance regulator
14	SP_X100-C_14	Backrest
15	SP_X100-C_15	Seat
16	SP_X100-C_16	Hexagonal flange nut M8
17	SP_X100-C_17	End cap 30x30mm
18	SP_X100-C_18	Hexagon socket round head cap bolt M8x40
19	SP_X100-C_19	Seat post
20	SP_X100-C_20	Cross recessed countersunk head bolt M5x8
21	SP_X100-C_21	PVC bracket
22	SP_X100-C_22	Hexagon socket round head cap bolt M8x16
23	SP_X100-C_23	Washer M8-T2
24	SP_X100-C_24	Central axis
25	SP_X100-C_25	Central axis bushing
26	SP_X100-C_26	Left pedal
27	SP_X100-C_27	Hexagon socket flange bolt M8x20
28	SP_X100-C_28	Left crank
29	SP_X100-C_29	Left chain cover
30	SP_X100-C_30	Hexagon socket round head cap bolt M8x20
31	SP_X100-C_31	Rear stablizer cap
32	SP_X100-C_32	Rear stablizer
33	SP_X100-C_33	Belt tensioner
34	SP_X100-C_34	Cross recessed countersunk head bolt M6x 35
35	SP_X100-C_35	Pulley plate
36	SP_X100-C_36	Hexagonal flange nut M6
37	SP_X100-C_37	Cross recessed countersunk head Bolt M5x20
38	SP_X100-C_38	Hexagon socket round head cap Bolt M6x30
39	SP_X100-C_39	Big pulley wheel
40	SP_X100-C_40	Hexagon socket round head cap Bolt M6x60
41	SP_X100-C_41	Small pulley wheel
42	SP_X100-C_42	Main frame bushing
44	SP_X100-C_44	Locking knob
45	SP_X100-C_45	Bearing round plate
46	SP_X100-C_46	Bottom bracket parts
47	SP_X100-C_47	V-belt
48	SP_X100-C_48	Hexagonal flange nut M10
49	SP_X100-C_49	Sleeve 6mm
50	SP_X100-C_50	Sleeve for magnetic holder
51	SP_X100-C_51	Magnetic bracket
52	SP_X100-C_52	Magnetic bracket shaft M10
53	SP_X100-C_53	Fixation screw M6x45
54	SP_X100-C_54	Belt pulley
55	SP_X100-C_55	Screw nut M10 -T5
56	SP_X100-C_56	Right crank
57	SP_X100-C_57	Crank cap
58	SP_X100-C_58	Right pedal
59	SP_X100-C_59	Sensor bar
60	SP_X100-C_60	Cross recessed countersunk head bolt M5x10
61	SP_X100-C_61	Cross recessed countersunk head bolt M6x10
62	SP_X100-C_62	Right chain cover
63	SP_X100-C_63	Decorative chain cover
64	SP_X100-C_64	Front stablizer cap
65	SP_X100-C_65	Front stablizer

Number in explosion drawing	Item number	Description
Not in drawing	SP_X100-C_66	Handlebar complete
Not in drawing	SP_X100-C_67	Cross screw M6X10
Not in drawing	SP_X100-C_68	Cross screw ST3x8
Not in drawing	SP_X100-C_69	Allen key
Not in drawing	SP_X100-C_70	Mauel key
Not in drawing	SP_X100-C_71	Cross screw_1_ ST 5x19
Not in drawing	SP_X100-C_72	Cross screw_2_ST4x28
Not in drawing	SP_X100-C_73	Washer M5- T2
Not in drawing	SP_X100-C_74	Washer M10 - T3
Not in drawing	SP_X100-C_75	Washer M10 - T2
Not in drawing	SP_X100-C_76	Spring
Not in drawing	SP_X100-C_77	Cross screw M4x8
Not in drawing	SP_X100-C_78	Safety pin
Not in drawing	SP_X100-C_79	Cross screw M5x30
Not in drawing	SP_X100-C_80	Cross screw M6x20
Not in drawing	SP_X100-C_81	Rubber grommet
Not in drawing	SP_X100-C_82	Plastic grommet
Not in drawing	SP_X100-C_83	Cross screw ST3x18
Not in drawing	SP_X100-C_Screw set	Screw and tool set
Not in drawing	SP_X100-C_Manual	Manual